



# KRAFT&DELE

PROFESSIONAL



## STÓŁ ROBOCZY SPAVALNICZY KD639



Warning-To reduce the risk of injury, user must read instruction manual.




Warning




Pinch points

### COMPONENT LIST

- A. Welding table (1 pc)
- B. Handle (1 pc)
- C. M8\*25mm bolt set (2 pc)
- D. Ground stud (1 pc)




### Use steps



Before using, check that the table is horizontal to use as a work bench, pull out the lock pin to open the leg.



Hold the two connect bars in place for the first leg.



Hold the another two connect bars in place for the second bars.



Assemble the handle using the bolts C.

